### **LBNL Emergency Services Program**



# Ernest Orlando Lawrence Berkeley National Laboratory

# September 30, 2010 Guest House Evacuation Drill AFTER ACTION REPORT



September 2010 Security Emergency Operations Group Environment, Safety, and Health Division

# LBNL/Guest House Evacuation Drill

Approved By: Noyce E.	SA D	- 11-9-2010
Royce Saunders Emergency Services Manager Environment, Health and Safety Division	Date	
Approved By:	Lal	9 NOV 10
Dan Lunsford Security and Emergency Operations Group Environment, Health and Safety Division  Approved By:	Date Leader	1/-20-10
Doug Fleming Director, Environment, Health and Safety I	Date Division	

### EXERCISE AFTER ACTION REPORT EMERGENCY MANAGEMENT EXERCISE Guest House Drill 09/30/10

#### **Exercise Summary**

The Guest House, B23, at Lawrence Berkeley National Laboratory conducted an evacuation drill. The purpose of the drill was to validate the effectiveness of the emergency response organization in accordance with the site's emergency plan and procedures and the DOE Order 151.1C and to test the building fire alarm system.

The goal of the exercise was to evaluate the Emergency Response Organization (ERO), implement protective actions, and activate the B23 Building Emergency Team (BET).

### **Drill Participants**

Thomas Farrell, BM Barry Bain, BET Chris Olson, BET Jennifer Zerfas, BET Bill Llewellyn, Observer Gary Piermattei, Fire Marshall Anne Boynton, Evaluator Pam Jiles, Evaluator Jan McClellan, Exercise Director/Evaluator

### Findings/Improvement Items

There were no findings or corrective actions. The response was evaluated against 11 exercise objectives. 1 objective was not met (BET.2). 4 objectives were not applicable (BET.4, BET.8, BM.2, BET.10). 6 improvements were found (I11, I13, I14, I15, I16, and I4). 2 noteworthy practices were found (N3 and N4).

#### **Exercise Scenario**

Homeland Security Advisory Threat Level is Elevated - Yellow. The LBNL weather conditions are sunny and very hot, with slight breeze. It is a typical work day in progress.

The Guest House, B23, is testing the fire alarms system and will use this as an opportunity for training for their BET members. Employees and guests will be evacuated from the building and directed to the Emergency Assembly Area to await further instructions.

### **Exercise Objectives**

	Building Emergency Team						
Building E	Building Emergency Team was assigned and evaluated against 9 Exercise Objectives. They met						
5 of the ass	5 of the assigned objectives and failed to meet 1.						
Obj. Id.	Obj. Id. Objective Statement Results Comments						
BET.1	Given a building evacuation,	Met					
staff evacuated the building							
	safely in accordance with						

DET 2	MEPP 2009, 2.3.6.5 and BET Evacuation Guidelines. LBNL/PUB-540 Rev April 1, 2003, EPIPs 002-1, 002-8, 002.9, 004-1.	Not Met	II.6. Duilding 22 hog 2
BET.2	Given a building evacuation, staff exited building to designated assembly areas in accordance with MEPP 2009, 2.3.6.5 and BET Evacuation Guidelines. LBNL/PUB-540 Rev April 1, 2003, EPIPs 002-1, 002-8, 002.9, 004-1.	Not Met	designated Assembly Areas. Per the building manager's instructions, 2 staff members went to each assembly area. Housekeeping staff were redirected to the correct assembly area after initially assembling on the patio.
BET.3	Given a building evacuation, BET had their personal protective equipment (vests and hard hats) in accordance with MEPP 2009, 2.3.6.5 and BET Evacuation Guidelines. LBNL/PUB-540 Rev April 1, 2003, EPIPs 002-1, 002-8, 002.9, 004-1.	Met	
BET.4	Given a building evacuation, BET removed trauma kits from building in accordance with MEPP 2009, 2.3.6.5 and BET Evacuation Guidelines. LBNL/PUB-540 Rev April 1, 2003, EPIPs 002-1, 002-8, 002.9, 004-1.	Not Applicable	Trauma kits are located in the rescue box, not in the building.
BET.5	Given a building evacuation, BET removed radios from building in accordance with MEPP 2009, 2.3.6.5 and BET Evacuation Guidelines. LBNL/PUB-540 Rev April 1, 2003, EPIPs 002-1, 002-8, 002.9, 004-1.	Met	
BET.6	Given a building evacuation, BET conducted a sweep of the building in accordance with MEPP 2009, 2.3.6.5 and BET Evacuation Guidelines. LBNL/PUB-540 Rev April 1,	Met	

	2003, EPIPs 002-1, 002-8, 002.9, 004-1.		
BET.7	Given a building evacuation, BET conducted accountability and reported the results to the BET lead or incident commander in accordance with MEPP 2009, 2.3.6.5 and BET Evacuation Guidelines. LBNL/PUB-540 Rev April 1, 2003, EPIPs 002-1, 002-8, 002.9, 004-1.	Met	
BET.8	Given a building evacuation, BET shall make contact with the EOC in accordance with MEPP 2009, 2.3.6.5 and BET Evacuation Guidelines. LBNL/PUB-540 Rev April 1, 2003, EPIPs 002-1, 002-8, 002.9, 004-1.	Not Applicable	Not applicable, EOC not activated for drill. Discussed procedure with the BET members after the drill.
BET.10	Given an emergency, BET members provided first aid in accordance with MEPP 2009, 2.3.6.5 and BET Evacuation Guidelines. LBNL/PUB-540 Rev April 1, 2003, EPIPs 002-1, 002-8, 002-9, 004-1.	Not Applicable	No First Aid necessary for drill.

#### 

Not Applicable

First responders weren't part

of the drill. Discussed with

BM and BET members the

2009, 2.3.6.4 and BET Evacuation Guidelines. LBNL/PUB-541 Effective Date: April 1, 2003, EPIP 004-

Given an operational

will provide situational

emergency Building Manager

BM.2

Building Manager		
information to first responders in accordance with MEPP 2009, 2.3.6.4 and BET Evacuation Guidelines. LBNL/PUB-541 Effective Date: April 1, 2003, EPIP 004-1.	need for one person to be the point of contact with the first responders.	

# Participant Performance Summary

Organization	Number of Objectives	Met	Not Met	Findings	Improvement Items	Superior Performance	Noteworthy Practices	Not Applicable	Not Observed
Exercise Control and Evaluation	0	0	0	0	2	0	0	0	0
Building Emergency Team	9	5	1	0	2	0	0	3	0
Building Manager	2	1	0	0	2	0	2	1	0
Exercise Totals	11	6	1	0	6	0	2	4	0

# **Improvement Items**

Building Emergency Team			
Improvement Item	Recommended Action		
I15: Sweep of the first floor delayed. BET assigned to provide the sweep also assigned to sweep another floor, while another BET was directing guests to the emergency assembly area.  BET didn't have keys to doors to check rooms.	Review procedures and sweep assignments with B23 Building Manager and BET members. An Emergency Key Box will be purchased to allow all BET Members to have keys. (Sweep was delayed due to testing being done on the fire alarm system. The horns and strobes did not activate simultaneously which led to some confusion.)  Responsible Organizations: Emergency Services Program Completion Date: 02/28/11		
(Objective: BET.2) I16: Evacuees went to the patio or across the street during the drill instead of the emergency assembly areas.	Review evacuation procedures with staff and guests, revise if needed. Include revisions in BET training and retrain B23 BET members.  Responsible Organizations: Emergency Services Program Completion Date: 02/28/11		

Building Manager		
Improvement Item Recommended Action		
I13: BET members haven't had training in first aid,	BET members are required to take first aid, and fire	
CPR or fire extinguisher use.	extinguisher training. Emergency Services Program to track	
-	required training for BET members and develop a process for	

	reminding the BET member, BET Lead and eventually BET member's work supervisor.
	Responsible Organizations: Emergency Services Program Completion Date: 09/30/2011
I14: Emergency Assembly Area location is where the fire truck will be stationed when responding to	Review location of emergency assembly area and sign.
the Guest House. The sign is located behind a chain link fence.	Responsible Organizations: Emergency Services Program Completion Date: 12/31/2010

## **Noteworthy Practices**

Participant: Building Manager and Building Emergency Team

**Noteworthy Practice:** N3 The BM/BET had a roster available when the evacuation began, which provided accountability of the guests. Evacuation Assistance List available for first responders.

**Noteworthy Practice: N4** The BM/BET used radios to provide communications between BM and the BETs during the drill. This was very important to the evacuation efforts since they were covering 3 floors and 2 emergency assembly areas.